

ToppersNotes



PRODUCTION ENGINEERING (MATERIAL SCIENCE)

VOLUME-IV

Sierra Innovations Pvt. Ltd.

Contents

**PRODUCTION ENGINEERING
(MATERIAL SCIENCE)**


1-341


The process of metal cutting in which the chip is formed affected by a relative movement between workpiece & hold edge of the cutting tool.

The relative movement is produced by a combination of Rotary & translatory movement of either the workpiece or tool.

M/C TOOL	RM (Relative movement)	
	W	T
1) LATHE	R	T
2) SHAPER PLANER	T	T
3) DRILLING	fixed	R & T
4) MILLING	T	R
5) S. Grinding Surface	T	R
6) C. Grinding cylindrical	R & T	R

LATHE:-





LATHE SPECIFICATIONS

- 1) HEIGHT OF CENTRES
- 2) SWING OVER BED
- 3) SWING OVER CARRIAGE
- 4) SWING OVER GAP
- 5) DISTANCE B/W CENTRES
- 6) LENGTH OF BED
- 7) NO OF SPEEDS, FEEDS ETC.

TYPES OF LATHE

i) Bench lathe:- Small lathe

ii) Speed lathe:- Speed lathe is that lathe where there is no carriage, no gearbox, no tool post.

iii) engine lathe:-

iv) tool room lathe:- Used for tool room. Used to make dies and jigs. Used in production.

mass production lathe
Bench lathe:-


It is very small lathe and it is mounted on a separately bench or cabinet and used for small work.

Speed lathe:- they do not have provision for ~~power~~ power feed and have no gear box, or carriage or lead screw. these are used for good turning, polishing, wood turning, metal screening etc.

engine lathe:- in olden days lathe is driven by steam engine. hence the name is still in existence even after modern lathes are provided with motor drive.

tool room lathe:- it is nothing but engine lathe provided with some extra attachment for accurate and precision work like taper turning attachment, collets, follower rest etc.

Capstan & Turret Lathe:- (mass production lathe)



In turret lathe ^{dissecting} gives to the foundation

heavy workpieces mass production

they earned

These are Semi-Automatic type machines Very Useful for mass production. they Carried special mechanisms for indexing the turret. (angular rotation)

Turret Lathe

- i) the turret head (square or hexagonal) is mounted on the saddle.
- ii) the above arrangement gives the rigidity as forces are transferred to the bed. hence this is capable handling heavy jobs and severe cutting condition.
- iii) tool travel is along entire bed length
- iv) tool feeding is slow & causes more fatigue to the operator hands.
- v) No tail stock.


Capstan Lathe

easy to manufacture

- i) the turret head (round or square or hexagonal) is mounted on a auxiliary slide. the moves on the auxiliary slide ways provided on the saddle.
- ii) Less rigidity, vibration occurs and hence suitable for lighter & smaller jobs.
- iii) tool travel is limited because of auxiliary slide travel limitation.
- iv) tool feeding is fast & causes less fatigue to the operators hands.
- v) No tail stock.

Automatic Lathe:-

these are design so that all the working and job handling movements of the complete manufacturing process for a job are done automatically. no participation of operator is required during the operation. they have single spindle & multi-spindle and classified in to Bar automatic



chucking automatic based on the size of raw material. They fall in the categories of heavy duty, high speed

Lathe Used in small production ^{Topper's notes} Geneva mechanism is used for indexing the turret

Special purpose lathe:- these are design to performed ^{certain} ~~specific~~ ^{work} Specity. only ex:- facing lathe, crankshaft lathe etc.

Work holding Device:-

1) CHUCKS :-

3 JAW

4 JAW

COLLET

chucking
Automatics

Used
for

PNEUMATIC

MAGNETIC

VACUUM



only
for Bar Stocks.
↓
Small rods.

Used for
S. Grinding
mic



Used
for

Very fast
clamping
and
non-clamping
operation.

IN TOOLROOM LATHES, BAR
AUTOMATICS, VERTICAL MILLING
MIC TO HOLD ENDMILLS




2) FACE PLATE




every sliding element
have a screw
nut.

3) CENTRES → LIVE
→ DEAD




5) CARRIER DOGS





4) MANDRELS

6) STEADM REST Toppersnotes



7) FOLLOWER REST




→ max size of collet is 40mm fixed size
 Collet is always in open condition.

In pneumatic

→ face plate is holding the workpiece. there is no jaws.
 hold → Round, Square, Rectangle

* mandrel is like shaft which supported hollow wps.
 it is a specific device.



a) SWIVELING THE COMPOUND REST

ANY ANGLE, ANY LENGTH

b) TAIL STOCK SET OVER

SMALL ANGLE, LONG JOB

c) FORM TOOL

tail stocker width is limited


ANY ANGLE, SHORT JOB

d) COMBINED FEEDS

45° CHAMFERS




e) TAPER TURNING ATTACHMENT

SMALL ANGLE, LONG JOB




When make angle 0° compound slide is parallel to Saddle.

When make angle 90° parallel to Compound slide. helps you in taper turning.



$$\sin \theta = \frac{s}{L}$$




Combined feeds based on engineering mechanics.

$\theta = 45^\circ$ if magnitude is same.


Tape turning attachment holding the job in centre. rotate the cross slide.

4) FACING




DIA is not effected
length / thickness is 1)


5) KNURLING



6) SPINNING



7) SPRING WINDING



Time estimation Toppersnotes

(i) Time for machining:- $T = \frac{L}{f \times N} = \frac{L}{f_m} = \text{min}$

Where $L = \text{length of cut} \rightarrow \text{mm}$

$f = \text{feed} \rightarrow \text{mm/rev}$

$f_m = \text{feed per min}$
mm/min

(2) $V = \frac{\pi D N}{1000}$

$V = \text{cutting speed}$

$= \text{m/min}$

$D = \text{starting dia of the workpiece}$

$\phi 4 \text{cm} - \phi 3 \text{cm}$

$= \frac{4+3}{2} = 3.5$

(3) $d = \frac{D_i - D_f}{2}$

$d = \text{depth of cut}$

(4) $P \text{ (or)} W \cdot D = F_c \cdot V = \text{Nm/min}$

$F_c = \text{cutting force}$

$V = \text{cutting speed}$

$F_c = K \cdot d \cdot f$

$K = \text{material constant}$

$d = \text{depth of cut}$

$f = \text{feed}$

(5) Time for threading

$= \text{Time per cut} \times \text{No. of cuts}$

$\text{Time per cut (Time/cut)} = \frac{L}{P \times N}$

Where $L = L_1 + AL + OT$

$P = \text{Lead}$

extra distance travelled by the tool to engage the w.p

extra distance travelled by the tool to disengage the w.p

$$P = \frac{1}{\text{No. of Threads / Unit length}}$$

(6) Time for drilling

$$T = \frac{\pi D L}{1000 f V}$$


assume

where D = dia of the drill
 L = depth of hole

(7) Time for Boring

$$T = \frac{\pi D L}{1000 f V}$$

where D = starting dia of the hole
 L = depth to be bore.



- Boring is next operation after drilling.
- We can't apply heavy cuts in Boring. Boring is always time taking. Smaller the depth of cut higher the surface finish.
- In Drilling surface finish is less compare to Boring.
- if surface finish is co Boring is Used.
- Boring is like internal turning

(8) Time for facing


$$T = \frac{L}{f \times N}$$

where $L = \frac{D}{2}$

ii) estimate the machining time to turn an m.s rod from 4 cm dia to 3.5 cm dia up to length of 15 cm in a single cut assume cutting speed 30 m/min, feed 0.4 mm/rev

Solⁿ: $\phi 4 - \phi 3.5$
 $D = 4, L = 15$
 $T = 1.58 \text{ min}$

iii) for the time required to turn a 60 mm dia rod into dimension shown taking cutting speed 20 m/min. feed 1.2 mm/rev all cuts are 3 mm D.



depth of cut control the upper. lower limit decided the availability of material.

Solⁿ

	D	L
1)	$\phi 60 - 54$	215
2)	$\phi 54 - \phi 48$	115
3)	$\phi 48 - \phi 42$	115

$$T_1 = \frac{\pi D L}{1000 f v} = \frac{\pi \times 60 \times 215}{1000 \times 1.2 \times 20} = 1.6886$$

$$T_2 = \frac{\pi D L}{1000 f v} = \frac{\pi \times 54 \times 115}{1000 \times 1.2 \times 20} = \cancel{0.519} 0.81288$$

$$T_3 = \frac{\pi D L}{1000 f v} = \frac{\pi \times 48 \times 115}{1000 \times 1.2 \times 20} = \cancel{0.350} 0.7225$$

$$T = T_1 + T_2 + T_3 = 3.2229 \text{ min}$$

iii) find the time required for threading on a 3 cm spindle of m.s of a length of 15 cm. ~~number~~ no of threads to be cut are 3/cm the lathe run at 88 rpm. assume approach & overtravel. 0.5 cm each. no of cuts for


Sol:-

$$T = \frac{L}{P \times N}$$

$$\begin{aligned} L &= L_1 + AL + OT \\ &= 15 + 0.5 + 0.5 \\ &= 16 \text{ cm} \end{aligned}$$

$$T = \frac{16}{\frac{1}{3} \times 88} \times 7 = 3.82 \text{ min.}$$

Q. find the time required for drilling a component shown in the figure: cutting speed 20 m/min, feed 0.02 cm/rev.

Sol:-

	D	L	
$T_1 = \phi 10$		120	$T_1 = \frac{\pi \times 10 \times 120}{1000 \times 0.02 \times 10 \times 20} = 0.94247$
$T_2 = \phi 20$		40	$T_2 = \frac{\pi \times 20 \times 40}{1000 \times 0.02 \times 10 \times 20} = 0.6283$

$$T = 1.58 \text{ min}$$


Q. A hollow spindle is to be bored to enlarge its hole dia from 2.5 cm to 3 cm up to 12 cm depth in a single cut. estimate the boring time if cutting speed 30 m/min and feed 0.02 cm/rev

Sol:-

$$D \rightarrow 2.5 - \phi 3$$

$$T = \frac{\pi D L}{1000 f V} = \frac{\pi \times 2.5 \times 12}{1000 \times 0.02 \times 10 \times 30} = 1.58 \text{ min}$$

Q. find the time required to face both end of a component shown in one cut. assume rpm 100, tool feed = 0.03 cm/rev,



Toppersnotes
In cylinder only two faces

$$\text{Time / face} = \frac{L}{f \times N} = \frac{D/2}{f \times N}$$

$$\therefore \text{total time} = \frac{D/2}{f \times N} \times 2 = 1.33 \text{ min}$$

Q. The roughing speed & finishing speed for turning a job 30 m/min & 60 m/min the respective feeds are 0.24 mm/rev & 0.1 mm/rev. the max depth of cut is 2mm, min depth of cut is 0.75 mm take material constant 1600 N/mm². Calculate power required for roughing & finishing in watt.

Sol:-

$$F_c = k \cdot d \cdot f$$

$$(F_c)_r = 1600 \times 2 \times 0.24$$


$$= 768$$


$$(P)_r = 768 \times 30$$

$$= 23040 = 384 \text{ watt}$$

$$(P)_f = \frac{1600 \times 0.75 \times 0.1 \times 60}{60}$$

$$= 120 \text{ watt}$$






- generating flat system.
- here converted rotary to Reciprocating motion.
- cutting is not continuous in this process.

BULL GEAR

- It reducing the speed. We are using simple gear train.
- reducing speed are used in Reciprocating motion.



they are using table feed.

Shaper is a reciprocating

type of machine tool used for producing flat surfaces. The tool is given reciprocating motion while the work is given feed. The tool is single point tool similar to lathe. → This is used for initial rough machining.

RATCHET & PAWL

Types

- i) A/c to the type of mechanism used for giving reciprocating motion to the RAM.
 - A) crank shaper or crank type
Rack & pinion crank & oscillating lever mechanism
 - B) geared shaper
Rack & pinion

Relation to frame motion

c) Hydraulic Shaper ^{Topper notes} constant speed is constant

By Hydraulic power oil is pumped into a piston with piston cylinder arrangement. any stroke length we

Q) A/c to the position and travel of the Ram will set.

A) Horizontal Shaper / Ram reciprocates in horizontal axis.

B) Vertical Shaper / Ram reciprocates in vertical axis.

C) Travelling head type shaper / the Ram moves cross wise feed during reciprocation and it is used for heavy job where table feed is not possible.

3) A/c to the type of design of the table.

A) Standard Shaper / table has two movement.

(Left & Right
Up & down)

B) Universal Shaper / In addition to above two movements the table can be swivelled about a horizontal axis parallel to the Ram guide way and upper portion of the table can be tilted about a second horizontal axis to the first.

Specifications

(i) max length of stroke or cut width \rightarrow table movement

(ii) table size length \rightarrow Ram "

(iii) return time to cutting time ratio.

(iv) no of speed & feeds

(v) floor space required.




(vi) weight of the machine etc.

Operations

i) Maching of horizontal, vertical & angular surface

ii) cutting slots, groove, keyways, Crease, splines,

↓
External.



Time estimation:-

1) cutting speed

$$V = \frac{NLR(1+m)}{1000}$$

where L = length of cutting stroke mm

m = ratio of return and to cutting time

N = NO of double strokes/min

(one cutting stroke + one return stroke)

NOTE:- (i) in actual practice cutting speed changes during the cutting stroke in the crank type & geared type shapers. Hence sometime the avg. cutting speed can be expressed as

$$V_{avg} = \frac{NLR(1+m)}{2 \times 1000}$$

(ii) in hydraulic shaper constant speed is possible during the stroke & also any stroke length can be set.

2) total time for one complete cut:-

$$T = \frac{LW(1+m)}{1000fv}$$

W = width of the workpiece

f = feed mm, mm/cutting stroke, mm/double stroke

SAME

3) MRR :-

$$MRR = 1000 Vfd \text{ mm}^3/\text{min}$$